

## **T-036 Inspection Limits and Repair**

## **INSPECTION**

P/N(s): E6896408 & E23076531

Revision: D Issued: 2/03/16

## **Spline Lock Nut**

**Engine Application(s)** 

**E6896408:** 250-C28B, C28C, 250-C30, C30G, C30G/2, C30M, C30P, C30S

**E23076531:** 250-C28B, C28C, C30, C30G, C30G/2, C30M, C30P, C30S, C30R, C30R/1, C30U, C40B,

C47B, C47M

**Subject:** Inspection and Rework Procedures for the E6896408 & E23076531 Spline Lock Nut.

**Compliance:** Any time the Spline Lock Nut is removed for overhaul.

**Notes:** Refer to OEM's published data for installation, engine operation and disassembly.

**Revisions:** N/C Dated: 9/07/97 Initial release.

A Dated: 1/29/01 Updated format.

B Dated: 8/12/05 Added P/N E23076531.C Dated: 9/04/09 Updated EXTEX to TIMKEN.

D Dated: 2/03/16 Updated Timken to EXTEX Engineered Products.

Discard and replace the Spline Lock Nut.